

Casino Aerodrome, Neville Bienke Memorial Drive, Casino

- Non-certified aerodrome
- FULL NOTAM SERVICE NOT AVAILABLE
- Refer to ERSA for aviation details for this aerodrome on the Air Services Australia website ([www.airservicesaustralia.com/aip/aip.asp](http://www.airservicesaustralia.com/aip/aip.asp)).
- Pilots intending to visit Casino Aerodrome are reminded they are obligated to check the status of the airport via telephone numbers listed with ERSA.
- Runway 10/28  
Length 1030m  
Width 30m
- The condition of the runway surface is bitumen sealed, there are no obvious potholes or defects, very low use and not regularly inspected
- Landing fees apply – for further information please phone (02) 6660 0300
- There is no fuel available
- Caution: alternate ground users i.e. driver training – for further information please phone (02) 6660 0300



For pilot enquiries:

Richmond Valley Council. Locked Bag 10, Casino NSW 2470

Telephone (02) 6660 0300, Fax (02) 6660 1300

Email: [council@richmondvalley.nsw.gov.au](mailto:council@richmondvalley.nsw.gov.au)

For further information phone Richmond Valley Council on (02) 6660 0300, email [council@richmondvalley.nsw.gov.au](mailto:council@richmondvalley.nsw.gov.au) or visit [www.richmondvalley.nsw.gov.au](http://www.richmondvalley.nsw.gov.au)

*DISCLAIMER: This fact sheet is for general information purposes only. While all care has been taken to ensure the information is correct, Richmond Valley Council accepts no responsibility for damage caused by this information, nor liability accepted for any unauthorised use of the information contained herein.*