



Certificate Of Analysis

Client: Richmond Valley Council
Address: Locked Bag 10
Casino NSW 2470
Contact: Sandeep Chugh
Sampled by: Client
Subcontract Laboratory: Envirolab (NATA2901)
Subcontract Reference: 277839

Final report

Report no: 21/1161
Date received: 18/08/2021
Testing commenced: 18/08/2021
Date reported: 15/09/2021
No. of samples: 2
Revision no: 01

Analysis results apply to samples as received.

Raw and Finished Weekly

Sample No.: Sample description:	Unit	LOR	21/1161-1 RVC Finished Water 18/08/2021 11:30	21/1161-2 RVC Raw Water 18/08/2021 09:30
Date sampled:				
Time sampled:				
Alkalinity (as CaCO ₃)	mg/L	20	127	141
Aluminium (Dissolved)	mg/L	0.005	0.032	0.033
Aluminium (Total)	mg/L	0.005	0.032	0.24
Calcium	mg/L	0.1	28.4	29.9
Colour (Apparent)	Pt-Co	2	<2	50
Colour (True)	Pt-Co	2	<2	13
<i>E.coli</i>	MPN/100mL	1	<1	27
Electrical Conductivity	µS/cm	1	420	380
Fluoride - ISE	mg/L	0.05	1.15	[NA]
Hardness as CaCO ₃	mg/L	1	142	148
Heterotrophic Plate Count	MPN/mL	2	<2	120
Iron (Dissolved)	mg/L	0.005	<0.005	0.16
Iron (Total)	mg/L	0.005	<0.005	0.38



Certificate Of Analysis

Client: Richmond Valley Council


Report no: 21/1161

Sample No.: Sample description:	Unit	LOR	21/1161-1 RVC Finished Water 18/08/2021 11:30	21/1161-2 RVC Raw Water 18/08/2021 09:30
Magnesium	mg/L	0.1	17.3	17.8
Manganese (Dissolved)	mg/L	0.005	<0.005	0.039
Manganese (Total)	mg/L	0.005	<0.005	0.042
pH	pH		7.3	7.9
Suspended Solids	mg/L	1	<1	9
Total Coliforms	MPN/100mL	1	<1	9,208
Total Dissolved Solids by calc	mg/L	2	269	243
Total Organic Carbon*	mg/L	1	1	<1
Turbidity	NTU	0.1	<0.10	5.9

End of results

General comments: This report must not be reproduced except in full. This report relates to items tested as specified herein.
 Samples tested between date received and date reported. Accredited for compliance with ISO/IEC 17025 - Testing
 # NATA accreditation does not cover the performance of this service. Tests marked with * are subcontracted.
 LOR denotes 'Limit of Reporting' < denotes less than; > denotes greater than; ND denotes 'not detected'
 The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards

Specific comments: This is the final report that supersedes the preliminary report issued on the 3.9.21


 M Window
 Laboratory Analyst
 Approved Authoriser